

* cutting speed, feed and depth of cut.

* cutting speed.

→ The cutting speed is defined as surface rate of travel of cutting edge relative to WIP.

→ It is expressed in metres per second or metres per minute.

→ The speed selected for any operation depends on the work material, tool material, cutting fluid and type of cut.

→ Lower speed : use hard steels and softer mat. can be taken
Higher speed



* Lathe feed :-
Distance cutting tool advance along length of work for every revolution of the spindle.

→ mm / Revolution

Normal distⁿ from the surface being removed to the surface exposed by the cutting tool,

measured in mm

only one roughing and one finishing cut.



Thrust :- The force acting on an object perpendicular to the surface is called thrust.

cutting force
Thrust force

cutting force,
Radial force and
Thrust force (feed force)


ORTHOGONAL CUTTING

OBLIQUE CUTTING

- Single point cutting tools called O.C
- called two dimension
- cutting angle 90° to parallel
- cutting Area less on WIP
- Tool life Reduction Angle more
- Metal Remove less
- chip flow will light and flat
- spiral
- turning, Bore turning, slotting etc

- Multi point cutting tool
- three dimension
- cutting angle less than 90°
- cutting area more on WIP
- Tool life longer Reduction angle less
- Metal Remove more
- chip flow side wall and long curl.

Tool turning
 P_1 Feed force \rightarrow opposite direction
 P_2 cutting force \rightarrow feed direction



describing the work chip formation and types of chips :-

→ chips :- in cutting process remove metal on the work piece, like as small coil or Rig types Bilbom is called chips.

→ Types of chips :-

- (1) continuous chip
- (2) Built-up edge chips
- (3) Discontinuous chip

(i) continuous chip (Ductile metal)

→ continuous chip are usually formed at high rake angles and or high cutting speed
→ A good surface finish is generally produced
→ small depth of cutting
→ always used good cutting fluids

→ Advantage

→ shear of chip and tool interference is less
→ good surface finish
→ high speed and average speed
→ good surface finish
→ large rake angle
→ tool life increase and power less

The angle of the cutting force relative to the work. There are two rake angles, namely the back rake angle & side rake angle.

- ↳ Disadvantage (both of which help to guide flow)
- ↳ Always used High level cutting fluid used so cost increased
- ↳ Edge must be sharp like knife
- ↳ continuous chip use not always desirable particularly in automated machine operation has to be stopped to clear chips.

(2) Built-up edges chips. (cutting metal)

- ↳ BUE consists of layers of metal. From the WIP that are gradually deposited on the tool.
- ↳ BUE then become unstable and eventually break up.
- ↳ Rake angle less.
- ↳ BUE metal is carried away on the tool side of the chip.
- ↳ The rest is deposited randomly on the WIP surface.
- ↳ BUE result in poor surface finish.
- ↳ decreasing the depth of cut.

Advantage

- ↳ Less - Rake angle
- ↳ cutting speed is less.

- ↳ Disadvantage
- ↳ surface finish not good
- ↳ tool life decreased due to shear on WIP.

(3) Discontinuous chip (Brittle material)

↳ Discontinuous chips consists of segments that may be firmly or loosely attached to each other.

↳ These chips occurs when the hard, brittle material such as cast iron

- ↳ Small rake angle
- ↳ low cutting speed
- ↳ High depth of cutting
- ↳ may be not provided cutting fluid

Advantage

- ↳ Average surface finish
- ↳ low power used
- ↳ average tool life

Disadvantage :-

- ↳ surface finishing is not good
- ↳ tool life depends to due wear

* Functions and types of chip Breakers :-

Functions of chip Breakers.

↳ During machining operation, diffⁿ types and sizes of chip are produced from diffⁿ work mat.

↳ The chips obtained by machining brittle mat. like cast iron and majority of non ferrous metal are small and discontinuous and their disposal do not pose any problem with the operator.

↳ On the other hand while machining ductile material long homogenous, continuous chips are obtained. even continuous chip with built-up edge are also obtained.

↳ This chips create many difficulties and problems.

↳ will produce scratches on finished surface.

↳ they will not permit machining process on interface with the process.

Date _____

→ It is desirable that these continuous chips must be broken down into small segments so that disposal becomes easy. For this purpose chip breakers are used.

- main function on chip breaker
- (1) To control the sliding chips on tool face and also to direct the chip in proper direction.
 - (2) To break the chip.

→ The chip flow and its control is made possible by selecting proper rake angle and cutting angle.

→ To control the chip flow in groove is cut on tool face or a small piece of steel is fitted on the tool face.

→ These arrangement of providing groove or mounting a steel block is called chip breaker.

→ The chip Breaker will offer Resistance to chip flow by creating obstruction. This will force the chip to curl and ultimately Break into small pieces which can be easily disposed.

TYPES of chip Breakers.

- (1) Groove type
- (2) Obstruction type


(1) Groove type

→ Shallow grooves are cut by the side of the cutting edge of the tool which will break the continuous chip obtained from the WIP.

→ Groove types chip Breakers the width of the groove or step depends upon the feed rate.

→ The groove depth of 0.01 inch is kept.

→ Groove width is equal to feed or 1.5 times feed.




chip breaker

2. Obstruction type

mechanical obstruction

type chip breaker



These type of chip breakers provide obstruction in the chip flow and force them to curl and break into pieces.

The path of chip can be estimated considering the width and thickness of the chip breaker.

on carbide tipped tools inserts use mechanically clamped and they are adjustable according to the chip tool-combination. Thus they use more flexible in use.

(13) Kinematic chip breaking.

This arrangement is used in face turning machines. The facing tool is held in the holder and is connected with spring and pushes.

The pusher is driven by the cam because of this the tool feed receives additional reciprocating motion which assists in breaking.

the chips into small pieces.
In this arrangement chips of
diaⁿ thickness are obtained

- # Advantage of chip breakers.
- Helps in getting desired results.
- By proper selection of speed, feed and depth of cut combination, desired metal removed rate can be obtained.
- restricts the work rate as well as power consumption.
- Helps in maintaining almost constant production rate.
- Provides safety for operators and machine tool.

Disadvantages

- Groove type chip breaker weakens the tool.
- To provide the groove special types of grinding wheel is necessary.
- When cutting conditions alter, the groove type breaker will have to be replaced.
- It offers resistance in chip flow.
- increase cutting force.
- power consumption increase.

cutting fluid.

Need of cutting fluid.

cutting fluid improve machinability.

increase tool life

provided better WIP surface finish

Reduce in tool forces.

eliminate chip in the response

A fluid improves machinability through cooling and friction reduction of chip

Flushing

Dimensional Accuracy

* Properties of cutting fluid

(1) no ill effect on the normal lubrication of the m/c element

(2) ease of handling, preparation and concentration control

(3) Normal flushing of oil detergent action on the m/c pump and the fluid system

- (4) optimum service and min. cost
- (5) Routing and composition of WIP and m/c
- (6) Forming, smacking, fogging or mashing.
- (7) Development of odors.
- (8) Toxic or other effects on personnel
- (9) deterioration of paint or finish on m/c.

* Merchant's force circle diagram

Merchant's force circle is a method for calculating the various force involved in the cutting process. This will first be explained with vector diagrams these in turn will be followed by a few formulas.

(1) Set up $x-y$ axis labeled with forces and the origin in the centre of the page. The scale should be enough to include both the measured forces. The cutting force (F_c) is drawn horizontally and the tangential force (F_t) is drawn vertically.

(FORCES) and Angle

